

Remington®

Consumer Product Notification Remington Rimfire: 22 Thunderbolt® TB-22A 22 Long Rifle Ammunition

Remington has determined that two specific lot codes of **Remington 22 Thunderbolt®** ammunition may contain rounds with an insufficient crimp on the bullet. This issue is specific only to lot numbers: **S22BB1237** and **S22BC1237**. Handling or loading this **22 Thunderbolt®** ammunition could result in the separation of the bullet from the shell casing. In certain situations, this occurrence could render the firearm inoperable.

The lot numbers are located on the interior of the tuck flap of an individual box or along the exterior of a shipping case. Examples:



If you have recently purchased a box, brick, or case of **Remington 22 Thunderbolt®** ammunition with the specific lot numbers: **S22BB1237** or **S22BC1237**, Remington will exchange this ammunition at no charge. For questions, or to arrange for exchange and replacement of this **22 Thunderbolt®** ammunition, please contact the Remington Customer Service staff at: **1-800-243-9700, Prompt #3**.

Remington would like to apologize for any inconveniences or concerns that this issue may have created for our customers. We thank you for your continued support of Remington firearms and ammunition products.

Safety First

Always observe the Ten Commandments of Firearm Safety and wear approved eye and ear protection anytime you are shooting.

July 31, 2013